



MasterFormat: 07 26 16

APRIL 2018
(Supersedes May 2009)

PMPC TAPE

Membrane Tape for Overlap Seams

DESCRIPTION

PMPC TAPE is a self-adhesive tape used in conjunction with the application of PREMOULDED MEMBRANE® VAPOR SEAL WITH PLASMATIC® CORE (PMPC). PMPC TAPE provides the same water permeance properties (.0011 perms) as PMPC, which is the lowest in the industry.

USES

PMPC TAPE is designed for sealing PMPC membrane seams and for attachment to footings, protrusions, etc.

FEATURES/BENEFITS

- Backing stabilized to resist the effects of UV exposure.
- Product is very conformable.
- Maintains a watertight seal in all weather conditions.

PACKAGING

PMPC TAPE is offered in 6" (152.4 mm) widths and roll lengths of 50' (15 m), six rolls per carton.

COVERAGE

One box of tape will adhere approximately 24 sheets of PMPC.

APPLICATION

Surface Preparation ... The PMPC TAPE area of adhesion should be free from dust, dirt, and moisture to allow maximum adhesion of the pressure-sensitive tape. The anti-stick sheet on PMPC should be removed prior to applying PMPC TAPE.

Sealing Seams/Attaching to Footing

... All lateral joints/seams in the membrane application can be overlapped and taped or butt-jointed and taped using 6" (152.4 mm) wide PMPC TAPE. The most efficient installation method includes placing PMPC on top of the footing and

against the vertical wall. This will sandwich PMPC between the footing, vertical wall, and poured concrete floor. This will help protect the concrete slab from external moisture sources once the slab has been placed.

Sealing Protrusions ... Cut a slit around pipes, ductwork, rebar, and wire penetrations to place the initial layer of the membrane. To further protect the concrete slab from external moisture sources, use a piece of PMPC and place a collar around these as well.

1. Cut a piece of PMPC a minimum of 12" (304.8 mm). The length should be 1 ½ times the pipe circumference. With a roofer's knife or scissors, cut "fingers" half the width of the film.
2. Wrap around and tape the collar onto the pipe and completely tape fingers to the bottom layer of PMPC.

In the event that PMPC is damaged during or after installation, repairs must be made. Cut a piece of the membrane large enough to cover any damage by a minimum overlap of 6" (152.4 mm) in all directions. Clean all adhesion areas of dust, dirt, and moisture. Tape down all edges using PMPC TAPE.

For most current data sheet, further LEED information and SDS, visit www.wrmeadows.com.

LEED INFORMATION

May help contribute to LEED credits:

- MRc9: Construction and Demolition Waste Management
- EAp2: Minimum Energy Performance
- EAc2: Optimize Energy Performance

CONTINUED ON THE REVERSE SIDE...

W. R. MEADOWS, INC.

P.O. Box 338 • HAMPSHIRE, IL 60140-0338
Phone: 847/214-2100 • Fax: 847/683-4544
1-800-342-5976
www.wrmeadows.com • info@wrmeadows.com

HAMPSHIRE, IL / CARTERSVILLE, GA / YORK, PA
FORT WORTH, TX / BENICIA, CA / POMONA, CA
GOODYEAR, AZ / MILTON, ON / SHERWOOD PARK, AB



LIMITED WARRANTY

W. R. MEADOWS, INC. warrants at the time and place we make shipment, our material will be of good quality and will conform with our published specifications in force on the date of acceptance of the order. Read complete warranty. Copy furnished upon request.

Disclaimer

The information contained herein is included for illustrative purposes only, and to the best of our knowledge, is accurate and reliable. W. R. MEADOWS, INC. cannot however under any circumstances make any guarantee of results or assume any obligation or liability in connection with the use of this information. As W. R. MEADOWS, INC. has no control over the use to which others may put its product, it is recommended that the products be tested to determine if suitable for specific application and/or our information is valid in a particular circumstance. Responsibility remains with the architect or engineer, contractor and owner for the design, application and proper installation of each product. Specifier and user shall determine the suitability of products for specific application and assume all responsibilities in connection therewith.